Sanitized Copy Approved for Release 2010/04/15 : CIA-RDP58-00453R000300020032-6

25 YEAR RE-REVIEW



STAT	17 September 1 862-616
	Ricotrical Rork - Tongo & Building
	It is kindly requested that the electrician install a two- way busser system between rooms 2002, 2004 and 2006 Tompo & Build- ing, in accordance with the accordance electric
	Those buseers are required for use in commotion with the telephones and should be installed as seen as possible.
STAT	phonic be one ented for particult detail.